



# Technical Service Bulletin

---

91 MIB3: configuration wizard appears without apparent reason

91 22 23 2067843/1 August 23, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
----------	------	-----------	----------------------------



# Technical Service Bulletin

---

A4, A4 allroad, S4, A5, A5 Sportback, A5 Cabriolet, S5, S5 Sportback, and S5 Cabriolet	2020 – 2022	All	With Audi connect and SOS
RS 5, RS 5 Sportback, A6, A6 allroad, S6, RS 6 Avant, A7, A7 e quattro, S7, RS 7, A8, S8, e-tron quattro, e-tron Sportback quattro, Q5, Q5 e quattro, Q5 Sportback, SQ5, SQ5 Sportback, Q7, SQ7, Q8, SQ8, and RS Q8	2021 – 2022		
A8 e quattro	2021		
A3, S3, RS 3, e- tron GT, RS e- tron GT, and Q3	2022		



# Technical Service Bulletin

---

## Condition

### Customer states:

The setup wizard is displayed every time the vehicle is started.

## Technical Background

The setup wizard has not been fully completed, therefore, it displays on every startup as designed.

## Production Solution

Not applicable.

## Service

**Do not perform any repairs. Any repairs for this concern may be denied.**

Instruct the customer that this condition is normal.

- The customer can either complete all steps in the setup wizard to fully personalize their vehicle.

Or

- The setup wizard can be deactivated via Settings >> Notifications, or via the notification shortcut in the drop-down menu (Figures 1 and 2).



# Technical Service Bulletin




Figure 1: Notification shortcut button in the dropdown menu.




Figure 2: Setup wizard deactivation setting.



# Technical Service Bulletin

---

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

## Additional Information

All part and service references provided in this TSB (2067843) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.