



VOLUNTARY SERVICE CAMPAIGN

Classification: BT22-013	Reference: NTB22-039	Date: May 19, 2022
-----------------------------	-------------------------	-----------------------

VOLUNTARY SERVICE CAMPAIGN 2013-2018 ALTIMA SEDAN; FRONT COMBINATION LAMPS (HEADLAMPS)

CAMPAIGN ID #: PC890
APPLIED VEHICLES: 2013-2018 Altima Sedan (L33)
APPLIED SYSTEMS: Front Combination Lamps (Headlamps) – Halogen ONLY

**Check Service COMM or Dealer Business Systems (DBS)
National Service History to confirm campaign eligibility.**

INTRODUCTION

Nissan is conducting this voluntary service campaign on certain specific model year 2013-2018 Altima sedan vehicles, to replace both combination lamp (headlamp) assemblies (Halogen only). This service will be performed at no charge to the customer for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number PC890 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

Dealers are to repair vehicles falling within range of this campaign that enter the service department. This includes vehicles purchased from private parties, vehicles presented by transient (tourists) owners, and vehicles in a dealer's inventory.

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Replace the headlamp assemblies.
 - For 2013-2015 Altima, refer to the ESM for the Sedan: **DRIVER CONTROLS > EXTERIOR LIGHTING SYSTEM > REMOVAL AND INSTALLATION > FRONT COMBINATION LAMP > Removal and Installation - Halogen**
 - For 2016-2018 Altima, refer to the ESM: **DRIVER CONTROLS > EXTERIOR LIGHTING SYSTEM > HALOGEN HEADLAMP > REMOVAL AND INSTALLATION > FRONT COMBINATION LAMP > Removal and Installation**
2. Perform headlamp aiming adjustment on the replaced headlamp assemblies.
 - For 2013-2015 Altima, refer to the ESM for the Sedan: **DRIVER CONTROLS > EXTERIOR LIGHTING SYSTEM > PERIODIC MAINTENANCE > HEADLAMP > Aiming Adjustment**
 - For 2016-2018 Altima, refer to the ESM: **DRIVER CONTROLS > EXTERIOR LIGHTING SYSTEM > HALOGEN HEADLAMP > PERIODIC MAINTENANCE > HEADLAMP > Aiming Adjustment**

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
LAMP ASSY – HEAD (RH) (Headlamp Assembly)	26010 - ***** (1)	1
LAMP ASSY – HEAD (LH) (Headlamp Assembly)	26060 - ***** (1)	1

(1) Refer to the Electronic Parts Catalog for the correct part number.

CLAIMS INFORMATION

Submit a “CM” line claim using the following claims coding:

CAMPAIGN (“CM”) ID	DESCRIPTION	OP CODE	FRT
PC890	REPLACE FRONT COMBINATION LAMPS (BOTH SIDES)	PC8900	1.2

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
May 19, 2022	NTB22-039	Original bulletin published