



VOLUNTARY SERVICE CAMPAIGN

Classification: BT22-012	Reference: NTB22-040	Date: May 19, 2022
-----------------------------	-------------------------	-----------------------

VOLUNTARY SERVICE CAMPAIGN 2013 ALTIMA COUPE; FRONT COMBINATION LAMPS (HEADLAMPS)

CAMPAIGN ID #: PC889
APPLIED VEHICLES: 2013 Altima Coupe (CL32)
APPLIED SYSTEMS: Front Combination Lamps (Headlamps) – Halogen ONLY

**Check Service COMM or Dealer Business Systems (DBS)
National Service History to confirm campaign eligibility.**

INTRODUCTION

Nissan is conducting this voluntary service campaign on certain specific model year 2013 Altima coupe vehicles, to replace both combination lamp (headlamp) assemblies (Halogen only). This service will be performed at no charge to the customer for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number PC889 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

Dealers are to repair vehicles falling within range of this campaign that enter the service department. This includes vehicles purchased from private parties, vehicles presented by transient (tourists) owners, and vehicles in a dealer's inventory.

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Replace the headlamp assemblies.
 - Refer to the ESM for the Sport Coupe: **DRIVER CONTROLS > EXTERIOR LIGHTING SYSTEM > REMOVAL AND INSTALLATION > FRONT COMBINATION LAMP > Removal and Installation - Halogen**
2. Perform headlamp aiming adjustment on the replaced headlamp assemblies.
 - Refer to the ESM for the Sport Coupe: **DRIVER CONTROLS > EXTERIOR LIGHTING SYSTEM > PERIODIC MAINTENANCE > HEADLAMP > Aiming Adjustment**

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
LAMP ASSY – HEAD (RH) (Headlamp Assembly)	26010-ZX10B	1
LAMP ASSY – HEAD (LH) (Headlamp Assembly)	26060-ZX10B	1

CLAIMS INFORMATION

Submit a “CM” line claim using the following claims coding:

CAMPAIGN (“CM”) ID	DESCRIPTION	OP CODE	FRT
PC889	REPLACE FRONT COMBINATION LAMPS (BOTH SIDES)	PC8890	0.8

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
May 19, 2022	NTB22-040	Original bulletin published