



TECHNICAL SERVICE BULLETIN

Classification: EM22-003	Reference: NTB22-042	Date: May 24, 2022
-----------------------------	-------------------------	-----------------------

FAN BRACKET SERVICE INFORMATION

APPLIED VEHICLES: 2020 Titan/Titan XD (A61)

SERVICE INFORMATION

If the Fan Bracket on an **APPLIED VEHICLE** is replaced for any reason, replace it with the part number listed in **PARTS INFORMATION** on page 2. Follow the updated torque sequence, as shown in Figure 2 on page 2.




Figure 1

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

FAN BRACKET TORQUE SEQUENCE




Figure 2

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
BRKT ASSY-FAN PULLEY	21046-1LA0C	1

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace Fan Bracket	(1)	CC42AA	**	**	(2)

- (1) Reference the Parts Information table above and use the Fan Pulley Bracket (21046-****) as the Primary Failed Part (PFP).
- (2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated Flat Rate Time (FRT).
- ** Use the Symptom and Diagnosis code appropriate for the repair performed.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
May 24, 2022	NTB22-042	Original bulletin published