# Service Alert

# Mazda North American Operations Irvine, CA 92618-2922



Subject:

FUEL DOOR STUCK CLOSED OR ALLEGEDLY FELL OFF BY ITSELF

Service Alert No.: SA-059/22

Last Issued: 08/23/2022

## **BULLETIN NOTES**

**APPLICABLE MODEL(S)/VINS:** 

2019-2022 Mazda3 2020-2022 CX-30 2023 CX-50

## **DESCRIPTION**

Some customers will report that their fuel door was stuck closed and would not open to refuel the vehicle. Follow the repair steps below unless the conditions outlined in **TSB 09-019/21 - FUEL-FILLER LID PANEL IS DEFORMED** are present.

## REPAIR PROCEDURE

- 1. Check for pry marks around the door opening. Did you see any pry marks?
  - **YES** This is due to outside influence and is not covered by Mazda warranty.
  - NO Continue to the next step.
- 2. Check the fuel door lock operation.
  - a. Lock the doors and verify if the fuel door lock is locking.

NOTE: The default setting is a 90-second delay after the doors lock, but the customer can set that to 0, 30, 60, 90, or 120 seconds.

b. Unlock the doors and verify if the fuel door lock is unlocking.

NOTE: There is no delay to this function, but the fuel door must be locked to confirm it is unlocking. See the lock note above.

- 3. Is the fuel door lock operation working correctly?
  - YES The fuel door repair is not covered by Mazda warranty.
  - NO Repair the fuel door lock concern and continue to the next step.
- 4. Refer to the owner's manual for that model and model year. Is it equipped with an emergency fuel door release?

**YES** - The fuel door repair is not covered by Mazda warranty.

**NO** - Repair the fuel door as a related part.

NOTE: If there is damage to the quarter panel, refer to STEP 1.

Page 1 of 1

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.