

BODY & CHASSIS

Ticking / Tapping Type Noise From Upper A-Pillar Area

21 – 22MY RR Sport

Customer Voice:

- A customer may report a ticking or tapping type noise while driving from the upper A-Pillar area.

Technical Description:

- This may be caused by a body flange contacting the windshield glass.

Status:

- Engineering is currently investigating this concern.
- SSM 75800 has been published to address this concern.
- The body flange can be easily be repositioned away from the windshield glass without the need to remove the windshield, using a suitable tool.
- Care should be used to avoid damaging the windshield glass.

