



TECHNICAL SERVICE BULLETIN

Classification: BT22-017	Reference: NTB22-075	Date: August 24, 2022
-----------------------------	-------------------------	--------------------------

DRIVER'S POWER SEAT RECLINES UNINTENTIONALLY

APPLIED VEHICLES: 2022-2023 Frontier (D41)

SERVICE INFORMATION

Refer to the information in this bulletin when diagnosing a customer concern of the driver's (LH) power seat recline position changing unintentionally on a 2022-2023 Frontier.

Not all customer concerns mean there are broken or malfunctioning parts. Use this information to help explain normal operation to the vehicle owner.

The driver's seat recline switch (Figure 1) can be bumped when exiting/entering the vehicle (Figure 2), resulting in unintentional recline of the seat upper.

Do not replace the side finisher/switch unless visible damage to the seat switch is present.




Figure 1



Figure 2

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
August 24, 2022	NTB22-075	Original bulletin published

