

## Wireless Apple Carplay cannot be started intermittently

---

Themen-Nummer	LI82.70-P-075186
Version	1
Funktionsgruppe	82.70 - Telefon, Sprachbediensystem (SBS)
Stand	18.08.22
Gültigkeit	Model Series 206, 223, 232, and 297
Änderungsgrund	

---

### Beanstandung

Customer states that wireless Apple Carplay intermittently may not initiate at start-up. The MBUX Display states "Apple Carplay could not be started. Your device has been connected as a bluetooth phone";

### Ursache

Current MBUX Multimedia System (A26/17) software

### Abhilfe

Updated MBUX Multimedia System (A26/17) software will be released in Q4 2022

Arbeitsnummern/Schadensschlüssel				
Arb.-Nr.	Arbeitstext	Zeit	Schadensschlüssel	Hinweis