


Model Series 167: ARTICO Seat Covers On Front Seat Torn/Cracked

Topic number	LI91.18-P-071629
Version	8
Function group	91.18 - Seat covers
Date	8/1/22
Validity	Model series 167 ARTICO man-made leather upholstery or ARTICO man-made leather upholstery/DINAMICA microfiber
Reason for change	Adjustment of remedy

Complaint

On vehicles with "ARTICO man-made leather upholstery" or "ARTICO man-made leather upholstery / DINAMICA microfiber - black (601A)" the material of the seat side bolster can tear. Both the seat cushion cover and the backrest cover on the front seat can be affected here.

Attachments	
File	Description
example1.jpg	Example 1
	
example2.jpg	Example 2



[example3.jpg](#)



Example 3

Cause

The material may tear because the material in the side bolster is not suitable.

Remedy

Optimized seat covers are now available for ordering with new part numbers.

Some supply constraints may exist during initial roll out.

Symptoms
Body > Seat > Seat cover > Chafed through
Body > Seat > Seat cover > Detaches
Operation numbers/damage codes

XENTRY TIPS

Op. no.	Operation text	Time	Damage code	Note
			91A0407	
			91N0407	