

Subject: Engineering Information - Oil Leaking From Oil Pan

This PI has been revised to end the need for information from the field. Please discard PIE0698.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 New (RPO J22, 12th VIN Digit = 5 or greater)	2022	2022	December 01, 2021	May 01, 2022	Equipped with 2.7L Engine (RPO L3B)	—
GMC	Sierra 1500 New (RPO J22, 12th VIN Digit = 5 or greater)						

If you encounter a vehicle with the above condition, refer to *Oil Pan Replacement* in SI.

Version	2
Modified	Released May 10, 2022 Revised August 24, 2022 - Ended the need for further information from the field.