

WMMO - Replacing A-pillar Trim Panel (Stop Delivery)

Vehicle Type: **Macan (95B)**

Model Year: **As of 2021 up to 2022**


Concerns: **A-pillar trim panel**

Information: **Due to a supplier error, a material that does not meet the required specifications was used for making the A-pillar trim panels on the affected vehicles.**

Action required: Replace A-pillar trim panels at the left and right.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Installation Position:



Installation position of A-pillar trim panel

Parts required

Parts Info:	Part No.	Designation	Qty.
	95B867233E OX7	⇒ A-pillar trim panel, left	1 ea.
	95B867234E OX7	⇒ A-pillar trim panel, right	1 ea.

Replacing A-pillar trim panels at the left and right

- 1 Replace A-pillar trim panels at the left and right.
⇒ *Workshop Manual 'Removing and installing A-pillar trim panel'*
- 2 Enter the campaign in the Warranty and Maintenance booklet.

Warranty processing

Scope 1:

Working time:

Replace A-pillar trim panels at the left and right.

Labor time: **55 TU**

Includes: Removing and installing side-section trim panel

⇒ **Damage Code WMMO 066 000 2**

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2022 Porsche Cars North America, Inc.