

Lubricant for Sunroof/Sliding Roof Mechanisms

Vehicles Affected

Model	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
All	All	All	N/A	N/A

Revision History

Revision	Release Date	Changes
0	August 8, 2018	Original document
1	August 30, 2022	Update of part number

Technical Background

Lubricant that is compatible with all roof systems is available.

Service Information

The old sunroof grease should be cleaned out thoroughly, leaving as little of the old grease as possible. Then the new grease should be applied to all moving contact points and worked in, ensuring that the new grease is contacting the moving components directly.

Part number: Isoflex Topas L32N or Klübersynth LI 44-22
 Please see *ATI - 7 2000 NVH Lubricant Kit - Part ID: 7000* for more information.

Search Items

Sunroof; sun roof; panorama roof; slider; grease; lubricate; squeaks; grinding

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.