ATTENTION:								
ALIENTIUN:		IMPORTANT - AII						
GENERAL MANAGER		Service Personnel						
PARTS MANAGER		Should Read and Initial in the boxes						
CLAIMS PERSONNEL		provided, right.						
SERVICE MANAGER		© 2021 Subaru of A	America	n Inc. A	All rights	reserv	ed	



18-226-21

M. 1. 7. 1.	SERVIC	CE BULLETIN	7 7	7
	SEIN	JE PULLETIN		, , ,

**APPLICABILITY:** 2013-22MY BRZ **NUMBER:** 

SUBJECT: Service Manual Corrections DATE: 08/22/22

## INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
		Engine Control	EFI System	Test Drive	Some Test Drive Descriptions Were Changed
		Wipers & Washers	Washer Motor	Installation	Step One of Installation Was Changed
		Lubrication	Lubrication System	Function Inspection	Standard Value Table Was Changed
2012	0040 007		Oil Pump Assy (FA20)	>Exploded	The Illustration, Removal Step16, and Installation Step 4 & 5 Were Changed
2013 BRZ	Intake / Exhaust	Air Cleaner Case Sub-Assy (FA20)	View >Removal >Installation	Air Cleaner Illustration, and Removal & Installation Procedures Were Added	
		Engine Mechanical	Partial Engine Assy (FA20)		The Illustration Was Changed
		Front Suspension	Front Suspension Lower Arm	Exploded View	The Illustration Was Changed
	Rear Suspension	>Rear Lower Arm >Toe Control Link		The Illustration Was Changed	

## CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

## SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
		Engine Control	EFI System	Test Drive	Some Test Drive Descriptions Were Changed
		Wipers & Washers	Washer Motor	Installation	Step One of Installation Was Changed
		Lubrication	Lubrication System	Function Inspection	Standard Value Table Was Changed
2014	BRZ	Lubrication	Oil Pump Assy (FA20)	>Exploded View >Removal	The Illustration, Removal Step16, and Installation Step 4 & 5 Were Changed
2014	DNZ	Intake / Exhaust	Air Cleaner Case Sub-Assy (FA20)	>Installation	Air Cleaner Illustration, and Removal & Installation Procedures Were Added
		Engine Mechanical	Partial Engine Assy (FA20)		The Illustration Was Changed
		Front Suspension	Front Suspension Lower Arm	Exploded View	The Illustration Was Changed
		Rear Suspension	>Rear Lower Arm >Toe Control Link		The Illustration Was Changed
		Engine Control	FFI Custom	Test Drive	Some Test Drive Descriptions Were Changed
		Engine Control	EFI System	DTC P2270 & P2271	The Wiring Diagram & #3 Inspection Step Were Changed
		Wipers & Washers	Washer Motor	Installation	Step One of Installation Was Changed
		Lubrication	Lubrication System	Function Inspection	Standard Value Table Was Changed
2015	BRZ		Oil Pump Assy (FA20)	>Exploded View >Removal	The Illustration, Removal Step16, and Installation Step 4 & 5 Were Changed
		Intake / Exhaust	Air Cleaner Case Sub-Assy (FA20)	>Installation	Air Cleaner Illustration, and Removal & Installation Procedures Were Added
		Engine Mechanical	Partial Engine Assy (FA20)	Exploded View	The Illustration Was Changed
		Front Suspension	Front Suspension Lower Arm	Exploded View	The Illustration Was Changed
		Rear Suspension	>Rear Lower Arm >Toe Control Link	Exploded View	The Illustration Was Changed
		Engine Control	ne Control EFI System	Test Drive	Some Test Drive Descriptions Were Changed
2016				DTC P2270 & P2271	The Wiring Diagram & #3 Inspection Step Were Changed
		Wipers & Washers	Washer Motor	Installation	Step One of Installation Was Changed
	DD7	BRZ Lubrication  Intake / Exhaust	Lubrication System	Function Inspection	Standard Value Table Was Changed
	BKZ		Oil Pump Assy (FA20)	>Exploded	The Illustration, Removal Step16, and Installation Step 4 & 5 Were Changed
			Air Cleaner Case Sub-Assy (FA20)	View >Removal >Installation	Air Cleaner Illustration, and Removal & Installation Procedures Were Added
		Engine Mechanical	Partial Engine Assy (FA20)	Exploded View	The Illustration Was Changed
		Front Suspension	Front Suspension Lower Arm		The Illustration Was Changed

Continued...

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE		
		Engine Control	EFI System	Test Drive	Some Test Drive Descriptions Were Changed		
				DTC P2270 & P2271	The Wiring Diagram & #3 Inspection Step Were Changed		
		Wipers & Washers	Washer Motor	Installation	Step One of Installation Was Changed		
		Lubrication	Lubrication System	Function Inspection	Standard Value Table Was Changed		
		Lubrication	Oil Pump Assy (FA20)	>Exploded View >Removal	The Illustration, Removal Step16, and Installation Step 4 & 5 Were Changed		
2017	BRZ	Intake / Exhaust	Air Cleaner Case Sub-Assy (FA20)	>Installation	Air Cleaner Illustration, and Removal & Installation Procedures Were Added		
		Front Brake	Front Brake	Installation	A Caution Was Added		
		Rear Brake	Rear Brake	(Brembo)	A Caution Was Added		
		Parking Brake	Parking Brake Assembly	Assembly	A Caution Was Added		
		Engine Mechanical	Partial Engine Assy (FA20)	Evaluded View	The Illustration Was Changed		
		Front Suspension	Front Suspension Lower Arm	Exploded View	The Illustration Was Changed		
		Engine Control	EFI System	Test Drive	Some Test Drive Descriptions Were Changed		
				DTC P2270 & P2271	The Wiring Diagram & #3 Inspection Step Were Changed		
		Wipers & Washers	Washer Motor	Installation	Step One of Installation Was Changed		
				Lubrication	Lubrication System	Function Inspection	Standard Value Table Was Changed
		Lubrication	Oil Pump Assy (FA20)	>Exploded View >Removal	The Illustration, Removal Step16, and Installation Step 4 & 5 Were Changed		
2018	BRZ	Intake / Exhaust	Air Cleaner Case Sub-Assy (FA20)	>Installation	Air Cleaner Illustration, and Removal & Installation Procedures Were Added		
		Front Brake	Front Brake	Installation	A Caution Was Added		
		Rear Brake	Rear Brake	(Brembo)	A Caution Was Added		
		Parking Brake	Parking Brake Assembly	Assembly	A Caution Was Added		
		Front Suspension	Front Suspension Lower Arm	Evaluded View	The Illustration Was Changed		
		Engine Mechanical	Partial Engine Assy (FA20)	Exploded View	The Illustration Was Changed		

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE	
			5510	Test Drive	Some Test Drive Descriptions Were Changed	
	Engine Control	EFI System	DTC P2270 & P2271	The Wiring Diagram & #3 Inspection Step Were Changed		
	2019 BRZ	Wipers & Washers	Washer Motor	Installation	Step One of Installation Was Changed	
2010		Lubrication	Lubrication System	Function Inspection	Standard Value Table Was Changed	
2019		Intake / Exhaust	Air Cleaner Case Sub-Assy (FA20)	>Exploded View >Removal >Installation	Air Cleaner Illustration, and Removal & Installation Procedures Were Added	
		Front Brake	Front Brake	Installation	A Caution Was Added	
		Rear Brake	Rear Brake	(Brembo)	A Caution Was Added	
		Parking Brake	Parking Brake Assembly	Assembly	A Caution Was Added	
		Front Suspension	Front Suspension Lower Arm	Exploded View	The Illustration Was Changed	
		Engine Control	EFI System	Test Drive	Some Test Drive Descriptions Were Changed	
		Engine Control		DTC P2270 & P2271	The Wiring Diagram & #3 Inspection Step Were Changed	
		Wipers & Washers	Washer Motor	Installation	Step One of Installation Was Changed	
0000	557	Lubrication	Lubrication System	Function Inspection	Standard Value Table Was Changed	
2020	DN∠	BRZ	Intake / Exhaust	Air Cleaner Case Sub-Assy (FA20)	>Exploded View >Removal >Installation	Air Cleaner Illustration, and Removal & Installation Procedures Were Added
		Front Brake	Front Brake	Installation	A Caution Was Added	
		Rear Brake	Rear Brake	(Brembo)	A Caution Was Added	
		Parking Brake	Parking Brake Assembly	Assembly	A Caution Was Added	
		Front Suspension	Front Suspension Lower Arm	Exploded View	The Illustration Was Changed	
		Engine Transmission/ Transaxle	Mechanical	Cylinder Block	Directions on Removal & Installation of Piston Pins Were Changed	
2022 BRZ				Rocker Cover >Installation	Some Changes Were Made To The Installation Procedures	
			Clutch System	Clutch Switch >Removal > Adjustment	Clutch Start Switch Protrusion Specification Was Changed	
	BRZ	BRZ Body & Electrical/ Wiring System	Exterior/Interior Trim	>Rear Bumper Installation >Trunk Garnish Assembly	Installation Cautions Were Added	
				Rear Quarter Trim >Removal & Installation	Some Descriptions & Illustrations Were Added	
		Diagnostics	Power Steering Diag	Diagnostic Procedure w/ DTC >C1551 >C1552	A Change Was Made to Step One Of These Trouble Trees	
			Body Control Diag	Customize >List	Auto Light Sensitivity Setting Value & Remarks Were Changed	