

# WNK9 Workshop campaign - Re-programming selector lever control unit

---

## WNK9 Workshop campaign - Re-programming selector lever control unit

ID Number	WNK9
Models	911 (992)
Model Years	2020-2022
VIN List	Attached
Number of Affected VINs	10,299
Issue Description	<p>Due to a software error, it is possible that the lights of the selector support buttons "M" and "P" will fail intermittently when actuated on the affected vehicles.</p> <p>If this happens, the lighting will remain switched off within one driving cycle. The function of the buttons and the transmission range display in the instrument cluster are unrestricted.</p> <p>To prevent this from happening, the selector lever control unit in the affected vehicles must be re-programmed with an updated data record.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles. <b>As of the time of this posting, the repair is immediately available.</b></p>
TI Number	<a href="#">No. 145-22</a>

### Required software

PIWIS Tester 3 test software version	41.200.040 (or higher)
--------------------------------------	------------------------

### Warranty processing

Validity:

WNK9 Workshop campaign - Re-programming selector lever control unit

This workshop campaign will be carried out up to August 5th, 2027 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code	WNK9 66 000
Repair Code	1
Labour time	41 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.