

WNIH7 Workshop campaign - Replace air conditioner pressure sensor

WNIH7 Workshop campaign - Replace air conditioner pressure sensor

ID Number	WNIH7
Models	Macan (95B)
Model Years	2021-2022
VIN List	Attached
Number of Affected VINs	2,927
Issue Description	<p>A pressure sensor which does not meet the required specifications may have been installed on the condenser for the air-conditioning system on the affected vehicles.</p> <p>This can result in restricted function of the air conditioning system.</p> <p>For this reason, the pressure sensor in the affected vehicles must be replaced.</p>
What dealers should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting, the repair is immediately available.</p> <p>Parts are now available and can be ordered as normal via PPL.</p>
TI Number	No. 123-22
Customer Notification	Will be posted at a later date

Parts required

Part number	Designation	Quantity / vehicle	Parts return*
V04015800AT	Pressure sensor	1 piece	No
V04015800CA	O-ring	1 piece	No

*The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the remanufactured parts process or be scrapped.

Warranty processing

Validity:

This workshop campaign will be carried out up to July 8th, 2027 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1-8:

Damage Code	WNH7 66 000
Repair Code	2
Labor time	329-474 time units

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service via WWS with the campaign scope.