

WNC6 Stop Delivery - Replace bracket for driver assistance systems

Update 8/15/22

Please be advised that parts can be ordered for all remaining vehicles via PPL with no PRMS ticket needed.

Update 5/31/22

Please be advised that parts have begun to be allocated for vehicles affected by WNC6. Please do not order parts.

Repairs can begin immediately upon the receipt of parts.

The TI is now available in PCSS and the [AfterSales Document Database](#).

WNC6 Stop Delivery - Replace bracket for driver assistance systems

ID Number	WNC6
Models	Taycan (Y1B)
Model Year	2021-2022
Number of Affected VINs	17
VIN list	Attached
Summary	Porsche is placing the subject vehicles on a Stop Delivery hold. The front mounting bracket for the assistance systems in the subject vehicles may not meet specifications and will need to be remedied prior to vehicle delivery.
What Dealers should do	Please do not deliver the subject vehicles until the repair is completed. The vehicles may be driven only for loading and unloading purposes in the transport chain prior to remedy.

WNC6 Stop Delivery - Replace bracket for driver assistance systems

Please do not attempt to order parts. Parts have been allocated on 5/31/22.

Repairs can begin as of 5/31/22.

TI Number

[No. 64-22](#)