

Subject		Market
2018-2022 GX460 Transfer Case Leak		USA
Service Category	Section	
Drivetrain	Transfer/4wd/Awd	
Applicability		
2018-2022 GX460		

APPLICABLE VEHICLES

2018-2022	GX460
-----------	-------

CONDITION

Oil may be found leaking from the transfer case input or rear output shaft seal as seen in the example pictures below:




Figure 1 Rear Output Shaft Seal Leak



Figure 2 Input Shaft Seal Leak

RECOMMENDATIONS

If you see this condition, please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references