



Thor Motor Coach Technical Service Bulletin

TSB #	TSB 22-10		
Description/Title:	Tuscany with optional motorized slide tray		
Affected Product Line(s):	Certain model year 2022 Tuscany		
Service Campaign # :	RC000274	Released Date:	
Codes:	Repair: TMCTS80277W	Document Date:	9/19/2022
Time Allowed:	Repair: 0.2	Document Revision:	

Issue:

Optional motorized slide tray movement signal delayed or no signal present at all.

Tools Required:

Screw driver

Part(s) Required:

0525067 - TSB 22-10 Tuscany slide tray kit

Instructions:

See attached repair instructions below.

1. Open baggage door and remove the switch cover and screws holding the switch bracket to the door.
2. Take the switch bracket and attach it to the side of the new bracket as shown below using the pre-drilled holes in the side of the new bracket.



3. Snap the switch cover back onto the bracket.
4. When remounting the new bracket, cover the existing holes in the baggage door with the new bracket and secure it with the provided screws.
5. See attached print below for additional information if needed.

