


Audi Vin-4-Pin Topic List



Topic Name	Model	Topic description	Information needed
All topics have associated worksheets to be filled out and attached to the TAC ticket. Worksheets can be found at: ServiceNet>>Technician References>>Vin-4-Pin>>Worksheets			
Coolant warning lamp	2020-2021 Q3	Customer states they receive a low coolant warning in the cluster. Coolant level appears to be full in the reservoir	<ul style="list-style-type: none"> Case does not relate to TSB 2061918 Photo showing reservoir level Complete reservoir, connector and 4 inch harness section
Active Air Shutter	2021-2022 Q7 and Q8	Check engine lamp is illuminated and DTC P05A000: Active Grille Air Shutter "A" Stuck is stored in the ECM.	<ul style="list-style-type: none"> P05A000: Active Grille Air Shutter "A" Stuck Photos of the shutter motor
PDC sensor connector loose at rear bumper	2022 Q3	One of the rear PDC sensor connectors is not fully seated.	<ul style="list-style-type: none"> DTC B107B13: Rear parking aid sensor Open circuit may be stored Untouched vehicles needed (with exception to removing the bumper) Photos of sensor connector as it was found and bumper harness label
PDC sensor connector loose	2022 A6	One of the front or rear PDC sensor connectors is not fully seated.	<ul style="list-style-type: none"> Untouched vehicles needed (with exception to removing the bumper) Photos of sensor connector as it was found and bumper harness label
Twisted seatbelts	2021-2022 A6,A7,A8,Q8 e-tron Quattro/SB	Front Seatbelts are twisted on new model vehicles	<ul style="list-style-type: none"> Photo of twisted seatbelt showing B-pillar and seat bottom in same frame of photo Photo of seatbelt deflector trim at shoulder height adjustment (see worksheet) <p>TAC case submitted with worksheet "Twisted seat belts"</p>
Noise from Front Door speaker Grill	2021 - 2022 A5	Noise from front door loudspeaker grille with music playback or while driving	<ul style="list-style-type: none"> Video of noise before repair is performed Photos of repair Photo of the sound settings in the MMI and the music genre/song



Audi Vin-4-Pin Topic List

			<ul style="list-style-type: none">• TAC case submitted with Worksheet “Noise from Front Door Loudspeaker Grille”
Noise from Front Door Trim Panel	2021 - 2022 e-tron quattro, e-tron Sportback quattro	Noise from front door trim panel while driving	<ul style="list-style-type: none">• Video of noise before repair is performed• Photos of repair TAC case submitted with Worksheet “Noise from Front Door Trim Panel”
ACC sensor misadjusted	2022 Q5	ACC warning shortly after PDI	<ul style="list-style-type: none">• Vehicles must have less than 600 miles• DTC C110300 Sensor misadjusted in DA 0013• Photo of bumper mold number (see worksheet)
 Note: Last revised 9/6/2022	<ul style="list-style-type: none">• Information requested in these worksheets update frequently. Please always use the latest worksheet located at AccessAudi>>ServiceNet>>Technician References>>Vin4Pin• Please include all information requested in the worksheet up front when submitting the WEB ticket to TAC.• Refer to TSB 2066297 Vin-4-Pin program for additional details.		