



**NUMBER:** 08-043-22 REV. A

**GROUP:** 08 - Electrical

**DATE:** March 10, 2022

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**This bulletin supersedes Technical Service Bulletin 08-043-22, date of issue March 02, 2022, which should be removed from your files. This is a complete revision and no asterisks have been used to highlight revisions.**

**SUBJECT:**

Flash: Heating Ventilation and Air Conditioning (HVAC) Updates

**OVERVIEW:**

This bulletin involves reprogramming the HVAC module with the latest available software.

**MODELS:**

2021 (WL) Jeep Grand Cherokee

**NOTE:** This bulletin applies to vehicles within the following markets/countries: North America.

**NOTE:** This bulletin applies to vehicles built on or before November 02, 2021 (MDH 1102XX) equipped ATC W/3 Zone Temp Control (Sales Code HAH) or ATC W/4 Zone Temp Control (Sales Code HAL).

**SYMPTOM/CONDITION:**

Customers may experience the following:

- High pitch whistle coming from the dash when the blower motor is turned on.

**NOTE:** High pitch whistle originated from the defroster door when the HVAC unit in either Hi-Level (panel and defrost) or Bi-Level (panel and floor) modes. May be worsened when running the front airflow at blower bar 1-2 and rear airflow at blower bar 5-7.

**DISCUSSION:**

The HVAC software update has been removed from wiTECH and is no longer applicable. Until a future software update can be released.

**POLICY:**

Information Only