

GPOP - Issue Review System

Part Number: 1RC63DX9A\$, 1RC63HL1A\$, 1RC64DX9A\$, 1RC64HL1A\$, 1RC65DX9A\$, 1RC66DX9A\$, 1RC66HL1A\$, 1RC67DX9A\$, 1RC68DX9A\$, 1RC68HL1A\$, 1RC69DX9A\$, 1RC69HL1A\$, 1RE03DX9A\$, 1RF12DX9A\$, 1RG01DX9A\$, 1RG01HL1A\$, 1UC571X9A\$, 1UC591DAA\$, 1UC591X9A\$, 1UC601DAA\$, 1UC601X9A\$, 1UC621DAA\$, 1UC641DAA\$, 1UC651DAA\$, 1UC651L1A\$, 1UC671DAA\$, 1UC671L1A\$, 1UC701DAA\$, 1UC711DAA\$, 1UC711L1A\$, 1UC721DAA\$, 1UC721L1A\$, 1UC731DAA\$, 1UC741DAA\$, 1UC751DAA\$, 1UC751L1A\$, 1UC761DAA\$, 1UC761L1A\$, 1UC771DAA\$, 1UC781DAA\$, 1UC781L1A\$, 1UC791DAA\$, 1UC791L1A\$, 1UK05DX9A\$, 1VS221L1A\$, 1VS221X9A\$, 1VS251DAA\$, 1VS311L1A\$, 1VS311U5A\$, 1VS371DAA\$, 1XL311SFA\$, 5LB481DAA\$, 5LB481L1A\$, 5LB531DAA\$, 5LB531L1A\$, 5LB561DAA\$, 5LB571DAA\$, 5LB591DAA\$, 5LB621DAA\$, 5LB631DAA\$, 5LB631L1A\$, 5LB651DAA\$, 5LB651L1A\$, 5LB661DAA\$, 5LN18DX9A\$, 5LN19DX9A\$, 5LN19ML2A\$, 5LN20DX9A\$, 5PL41DX9A\$, 5PL42DX9A\$, 5PL43DX9A\$, 5PL44DX9A\$, 5PL44ML2A\$, 5PL45DX9A\$, 5PL46DX9A\$, 5PL46ML2A\$, 5PL47DX9A\$, 5PL47ML2A\$, 5PL48DX9A\$, 5PL48ML2A\$, 5PS831DAA\$, 5PS831X9A\$, 5VD621D1A\$, 5VD621L1A\$, 5VD621S4A\$, 5VD621U5A\$, 5VD621X9A\$, 5VD631X9A\$, 5VD651SFA\$, 5VD841X9A\$, 5XU931X9A\$, 5XU941X9A\$, 5XU941XRA\$, 5XU951X9A\$, 5XU951XRA\$, 6UE481U5A\$, 6UM22DX9A\$

Part Description: Overhead Console

Issue If the sunglasses holder door in the overhead console will not stay closed, inspect
Description: the Latch for damage. The Latch is now released for service under part number
68599540A\$.