



## STAR ONLINE PUBLICATION




**Case Number:** S2208000123

**Release Date:** June 2022

**Symptom/Vehicle Issue:** Enhanced Security Radio Frequency Hub Module (RFHUB) Update, Negative Response 0x12 "Sub Function Not Supported"

**Discussion:** When flashing the RFHUB on a "Manual" transmission Dodge Challenger 2016 - 2018 the scan tool is responding with an ECU failed attempt Negative Response 0x12 "Sub Function Not Support". Engineering currently investigating the updates required to support the enhanced vehicle security RFHUB software update for these vehicles. The field will be notified when the updates become available.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**