

STAR ONLINE PUBLICATION















Case Number: S2223000046

Release Date: June 2022

Symptom/Vehicle Issue: Upper Glove Box Door Does Not Open When Button Is

Pressed

Discussion: If the upper glove box door intermittently doesn't open with the push button, the glove box is serviced as an assembly. Replace the whole upper glove box with the most current part shown in the Star Parts catalog. Refer to Service Library for removal and installation steps. 23 - Body / Instrument Panel / GLOVE BOX, Instrument Panel, Upper / Removal and Installation



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

FCA US LLC Version 4.4 11/05/2021