

Case Number: S22230000049

Release Date: June 2022

Symptom/Vehicle Issue: Water Drips Onto The Accessory Drive Belt and Freezes. Drive Belt May Come Off Pulleys Due To Ice

Discussion: If a customer has a vehicle with a Shaker Hood (AZS sales code) built before 6/15/2022 with a water/ice on accessory belt complaint, replace the Shaker Hood Base with 68233366AC or newer. Part number 68233366AC has a drain to divert the water away from the accessory belt.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

Stellantis US LLC





Updated Shaker Hood Base

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

Stellantis US LLC