

Case Number: S2223000050

Release Date: June 2022

Symptom/Vehicle Issue: Steering Wheel Not Hot Enough

**Discussion**: To test if the steering wheel temperature is acceptable, use an IR temp gun to measure surface temp. It should measure between 86-106 Degrees Fahrenheit. If it is in this range no repair is necessary and the heated wheel is operating as designed.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

Stellantis US LLC