



STAR ONLINE PUBLICATION




Case Number: S2224000008

Release Date: June 2022

Symptom/Vehicle Issue: Customer Indicates AC Blows Warm Air

Customer Complaint/Technician Observation: With the AC turned on the air blowing through the vents is warm.

Discussion: Using an UV light inspect AC lines for leaks at TXV valve port, AC charge ports and condenser fittings. (See image below for reference). If a leak is detected replace the O-ring only.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found