



**NUMBER:** 08-136-22

**GROUP:** 08 - Electrical

**DATE:** June 29, 2022

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**SUBJECT:**

Windshield Wiper Stuck In On Position

**OVERVIEW:**

This bulletin involves replacing the Steering Column Control Module (SCCM).

**MODELS:**

2021 (WD) Dodge Durango

**NOTE:** This bulletin applies to vehicles within the following markets/countries: North America.

**NOTE:** This bulletin applies to vehicles built on or after July 01, 2021 (MDH 0701XX) and on or before December 27, 2021 (MDH 1227XX).

**SYMPTOM/CONDITION:**

Customers may also experience the following:

- Windshield wiper stuck in on position.

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the one listed are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	7HJ35DX9AA	SCCM
1	06511907AA	Screw (Steering Wheel Bolt )

**REPAIR PROCEDURE:**

1. Replace the SCCM using a new steering wheel bolt. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info>08 - Electrical / 8E - Electronic Control Modules / Module, Steering Column Control (SCCM) / Removal and Installation.
2. Clear all DTCs that may have been set after SCCM replacement.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

<b>Labor Operation No:</b>	<b>Description</b>	<b>Skill Category</b>	<b>Amount</b>
08-19-27-90	Module, Steering Column Control - Replace (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.6 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------