

## 2022 Ascent

Complaint: black abs is leaking

cause: installed at a diagonal angle which isn't creating a good seal. abs glue broke loose

correction: R&R 90 degree elbow. 1.5 hrs + 46.75 parts (90 degree elbow, coupler, spigot flange, coupling abs, abs glue)

The time approved is 1.0 hour + \$ 46.75 parts cost