

## VOLKSWAGEN DEALER COMMUNICATION

## REVISION - UPDATE 24HV - Engine Control Module Software Update

This notice is for:

- Dealer Principal
- ✓ Service Manager
- ✓ Warranty Administrator

- General ManagerSales Managers
- ✓ Parts Manager
- ✓ Service Consultant
- ✓ Technicians

Date:

September 23, 2022

**Summary** 

A revised 24HV Update bulletin has been published with updated claiming and work instructions relevant to fault P0606.

If an ECM was ordered for a vehicle due to fault P0606 with symptom code 32902, technicians should follow the fault clearing procedure in the 24HV work procedure. *If the fault clearing procedure is successful, please cancel the order for the ECM.* 

Please see the revised bulletin for 24HV Update published in ELSA and ServiceNet for additional information.

-END OF MESSAGE-