

# Technical Service Bulletin

<b>Topic</b>	Noise from left hand side of the vehicle when actuating the brake pedal
<b>Market area</b>	Russische Föderation (5RU),Australia E04 Bentley rest Asia and Australia (6E04),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
<b>Brand</b>	Bentley
<b>Transaction No.</b>	2067598/1
<b>Level</b>	EH
<b>Status</b>	Released for publishing
<b>Release date</b>	Sep 20, 2022

## New customer code

Object of complaint	Complaint type	Position
chassis -> brakes, brake regulation -> anti-lock braking system (ABS)	noises, vibrations -> creaking	

## Vehicle data

### New Flying Spur Hybrid

#### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
ZG23GB	2022	E		*	*	*

## Documents

Document name
<a href="#">master.xml</a>

■

## Condition

### Customer statement

Noise from left hand side of the vehicle when actuating the brake pedal

## Technical Background

Refer to the video on the Bentley Hub referencing TPI 2067598/- noting the following:

The noise is normal operation of the ABS modulator, the modulator actuates with each brake input as part of the blending process between energy regeneration and foundation brake application

No further action/diagnosis is required

If the noise is as detailed within the video, the customer should be advised that this is normal and expected behaviour

□

**No further action/diagnosis is required**

## Production Solution

Not applicable

## Service

Refer to the Technical background section