SERVICE BULLETIN



M1552

2022-09-06

M1552: 2022 FLHRXS, FLHXS, AND FLTRXS WHEELS SUBSTITUTION

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Revision Description
2022-09-06	Description change: RR was FR.
	* Updated Part Numbers
2022-05-13	Initial release

Purpose for Service Bulletin

This bulletin informs dealers that Harley-Davidson will have a certain number of 2022 FLHRXS, FLHXS, and FLTRXS models built with alternative wheels.

These wheels are an approved substitution and no action should be taken to replace the alternate wheels with the original part numbers. Refer to Table 2.

Vehicles Affected

2022 Models: FLHRXS, FLHXS, and FLTRXS.

Markets Affected

CAN and DOM.

Part Numbers

Refer to Table 2.

Table 2. Part Numbers

Original Part No.	Item Description	Substitute Part No.		
43300630	WHL, FR, BLK 19 x 3.5	43300618		
40900606	WHL, RR, BLK 18 x 5	40900594		

Required Dealer Action

The part substitutions noted in this bulletin are approved substitutions for the vehicle's configuration.

If you have received a vehicle with the substituted parts, **DO NOT** order the original configured parts and **DO NOT** file a warranty claim for these parts at the time of delivery unless a defect or damage is found. If at any time, during the vehicles warranty the substituted part fails, the substituted part must be ordered and replaced. Refer to Table 2.

NOTE

The part number information in this bulletin may be different than what is reflected in the parts catalog.

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									