



Tips and Tricks Revision 13

Date: September 14, 2022
To: Dealer Principal, General Manager, Service Manager, North American Dealer Network
From: Richard Kenton, Technical Director
Dan Schwartz, Service Area Manager

Dear Dealers,

This bulletin is to notify you of important updates included with the recent release of Tips and Tricks Revision 13. A brief summary of each new addition is listed below, but please review the complete document hosted on DCS for further details. [Ducati - Bulletins](#)

Revision 13 New Additions		
#	Subject	Model Affected
1	Turn by Turn function availability	Desert X
2	Possible presence of scratches on the rear handle	Desert X
3	Handlebar crossbar fastening inside the crate	Desert X
4	Indications for fuel tank cap cover alignment	Multistrada
5	Error P0444 possible validation - Canister purge valve	Multistrada
6	Possible generator malfunctioning	Multistrada
7	Immobilizer error on instrument panel	All Models

This bulletin is only applicable for Ducati Motorcycles manufactured and configured for the Ducati North American market (USA, Canada and MX).

For questions about this Service Bulletin,
please contact your Service Area Manager.