

## Malfunction Of The Electric Steering Column Adjustment

---

Topic number	LI46.15-P-075284
Version	1
Function group	46.15 - Steering column adjustment
Date	9/12/22
Validity	Models 253, 293
Reason for change	

---

### Complaint

Malfunction of the electric steering column adjustment.

The adjustment application by the driver does not correspond to the adjustment direction of the steering column.

### Cause

Polarity reversal of the lines M20/1 (steering column adjustment motor, forward and backward) and M20/2 (steering column adjustment motor, upward and downward) results in a

malfunction of the electric steering column adjustment.

### Remedy

Check the lines (line colors) of M20/1 and M20/2 as per the WIS circuit diagram and correct if necessary.

<b>Symptoms</b>
Chassis/suspension > Steering system > Steering column adjustment > Does not adjust longitudinally
Chassis/suspension > Steering system > Steering column adjustment > Does not adjust in height
Overall vehicle > Power supply > Fuel cell > Malfunction

<b>Operation numbers/damage codes</b>				
Op. no.	Operation text	Time	Damage code	Note
			5908974	K/Z* steering column adjustment motor length adjustment
			5911274	K/Z* steering column adjustment motor height adjustment