ELECTRICAL



20-23MY Defender 21-23 MY Discovery, Discovery Sport, Range PIVI – USB Rover Evoque, New Range Rover, New Range Rover Sport, Velar, E-Pace, I-Pace, F-Pace, XF Customer Voice: USB stick not recognized when inserted into the Front Portable Media Interface Panel (FPMIP). This can occur in the following scenarios: - Installing maps at PDI - Updating the ICCM/IGM via service tools Media playback from a source connected via USB Technical Description: Under investigation Action: Please Do NOT attempt any repairs or reset the system until advised as engineering 1. requires logs. Refer to SSM75727, SSM75728 for further details. 2.