

BODY & CHASSIS

Loss of Function/ Hot Air From RH/ LH Side Of HVAC Vents

22– 23MY New Range Rover (L460)

Customer Voice:

- A customer may report that the HVAC vents on either the left hand or right hand side does not operate properly.

Technical Description:

- This may be caused by either LIN bus A or B of the HVAC system setting a fault for a missing message.

Status:

- Engineering is currently investigating this concern.
- SSM 75847 has been published to provide diagnostic guidance for this concern.
- Additionally, the SSM requests an EPQR be submitted with details from the provided diagnostic steps to aid in the ongoing investigation.

