

BODY & CHASSIS

Power Steering Assistance Reduced Message Displayed

17– 23MY Discovery, Defender

Customer Voice:

- A customer may report that an amber general warning indicator is illuminated and a warning message “Power Steering Assistance Reduced” is displayed on the instrument pack cluster.

Technical Description:

- A check for DTCs may find DTC B1304-04 – (Electronic Power Assisted Steering System – System Internal Failures) or B1304-17 - (Electronic Power Assisted Steering System – Circuit Voltage Above Threshold). This may be caused by an error in the Power Steering Control Module (PSCM).

Status:

- SSM 75704 has been published to provide diagnostic guidance for this concern.
- Please refer to this SSM should a customer express a concern.

