

WNL7 - Retrofitting Indicator Plate on Vehicle Electrical System Battery (Workshop Campaign)

Model Line: **Cayenne (9YA/9YB)**

Model Year: **2022**

Concerns: **Vehicle electrical system battery (indicator plate)**

Information: **An indicator plate on the 12-V vehicle electrical system battery was not affixed to the affected vehicles due to a process error.**

This indicator plate contains important information on leak protection for the vehicle electrical system battery.

Action required: Retrofit indicator plate on vehicle electrical system battery.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Parts required

Parts Info:	Part No.	Designation	Number
	PAB010006A	⇒ Indicator plate on battery	1 piece

Retrofit indicator plate on vehicle electrical system battery




Information

When working on the vehicle electrical system battery, observe general information on the 12-volt lithium-ion battery. ⇒ *Workshop Manual '2706IN General information on the 12-volt lithium-ion battery'*

Work Procedure: 1 Remove battery cover. ⇒ *Workshop Manual '271219 Removing and installing battery cover'*

- 2 Affix indicator plate on retaining bracket for the vehicle electrical system battery and proceed as follows: Place tab of the indicator plate around the retaining bracket, guide it into the slot provided and tighten it. ⇒ *Positioning indicator plate on vehicle electrical system battery*
- 3 Install battery cover. ⇒ *Workshop Manual '271219 Removing and installing battery cover'*
- 4 Enter the campaign in the Warranty and Maintenance booklet.



Positioning indicator plate on vehicle electrical system battery

Warranty processing

Scope 1: **Retrofit indicator plate on vehicle electrical system battery**

Labor time:

Retrofit indicator plate on vehicle electrical system battery

Labor time: **19 TU**

Includes:

Removing and installing battery cover

Required parts:

PAB010006A	Indicator plate on battery	1 piece
------------	----------------------------	---------

⇒ **Damage code WNL7 066 000 1**

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2022 Porsche Cars North America, Inc.