

# WNR3 Stop Delivery - Fuel collection pipes fastening screws quality inspection

---

## Update 9/30/22

Please be advised that repairs are now available for vehicles affected by WNR3. Parts are available via PPL order as needed.

The TI is available below and will not be posted in PCSS.

## WNR3 Stop Delivery - Fuel collection pipes fastening screws quality inspection

ID number	WNR3
Models	911 GT3 / 911 GT3 Touring (992) 718 Cayman GT4 RS (982)
Model Years	2022-2023
Number of Affected VINs	86
VIN list	Attached
Summary	<p><b>Porsche is placing the subject vehicles on a Stop Delivery hold.</b></p> <p>The fuel collection pipe fastening screws on both cylinder banks need to be replaced and tightened to factory specification prior to delivery.</p>
What Dealers Should do	<p><b>The inspection procedure is now available as of 9/30/22.</b></p> <p><b>Please do not deliver the subject vehicles until the repair is completed.</b></p> <p>The vehicles may be driven only for loading and unloading purposes in the transport chain prior to remedy.</p>

TI Number

TI posted below.

## Important information

**DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.**

### Repair measure:

Replace fastening screws for fuel collection pipes in accordance with Workshop Manual "243019 Removing and installing fuel collection pipe".

See attached remedy.

### Parts situation:

All necessary parts are available.

### Warranty processing:

Please invoice scope 1-3 for this campaign by submitting a campaign warranty claim. This will ensure that the campaign is documented in the systems as performed.

Scope 1: Only valid for 911 GT3

Damage code	WNR3 66 000
Repair code	2
Working time	1326 ZE

Scope 2: Only valid for 911 GT3 Touring

Damage code	WNR3 66 000
Repair code	2
Working time	1422 TU

Scope 3: Only valid for 718 Cayman GT4 RS

Damage code	WNR3 66 000
-------------	-------------

WNR3 Stop Delivery - Fuel collection pipes fastening screws quality inspection

Repair code	2
Working time	1291 TU