

Reference	SSM75727
Models	Defender / L663 Discovery / L462 Discovery Sport / L550 New Range Rover / L460 New Range Rover Evoque / L551 New Range Rover Sport / L461 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494 Range Rover Velar / L560
Title	21 MY Onwards PIVI PRO USB Inoperative Cross Car Line
Category	Electrical
Last modified	23-Sep-2022 00:00:00
Symptom	203000 Basic Electrical
Attachments	DLT logging procedure..pdf (DLT logging procedure..pdf)
Content	<p><u>Issue</u></p> <p>USB stick not recognised when inserted into the Front Portable Media Interface Panel (FPMIP). This can occur in the following scenarios:</p> <ol style="list-style-type: none"> 1. Installing maps at PDI 2. Updating the ICCM/IGM via service tools 3. Media playback from a source connected via USB <p><u>Cause</u></p> <p>Under investigation.</p> <p><u>Action</u></p> <p>Please Do NOT attempt any repairs or reset the system until advised as engineering require DLT logs, if this issue is observed, raise a TA & quote this SSM number for further assistance for the attention of (EES_200), then await further instructions.'</p>

anBhd#RlcnM7MjAyM0xMC0wNVQxNzozODo0N42MzVaOzEzN4yMjYhNzluMTI3Ow==