

Sent on 10 07 2022 Expires on 10 21 2022

From Technical Information & Support Group

Subject Request for Visit: 2021-2022 RDX Brake Noise (ACTION REQUIRED)

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
From: Technical Information & Support Group
RE: Request for Parts: 2021-2022 RDX Brake Noise (**ACTION REQUIRED**)

This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this iN message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda Motor Co., Inc. (AHM) is searching for certain 2021-2022 RDXs with a client complaint of a front and/or rear brake noise which can be described as a squeal. To better understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. For 2021, VIN must be after 5J8TC2H..ML009976 (4WD) or 5J8TC1H..ML004781 (2WD).
2. All 2022 VINS are accepted.
3. Must be able to duplicate the squeal noise.
4. Vehicle has not been involved in a collision.
5. Brake pads have not been replaced & the discs have not been turned or previously replaced.
6. No repair has been attempted for this issue.

Action Required

If a vehicle matching the qualifiers above comes into your dealership, please e-mail Technical Information & Support at tis@ahm.honda.com.

TIS will contact you to record certain vehicle information and provide you with further instructions.

Please be sure to include the following information in your e-mail.

E-mail Title:

1. Model Year (e.g. 2020)
2. Model Name (e.g. TLX)
3. Issue (e.g. Brake Judder)
4. VIN

E-Mail Body:

1. Dealer Number
2. Your Name
3. Best Phone Number to be Reached
4. Current Mileage

Thank you.