

Subject: Engineering Information - Disconnected Emission Reduction Fluid Exhaust Front Pipe Injector Supply Pipe, DTCs P249C, P20E8 Set

This PI has been revised to end the need for information from the field. Please discard PIE0665B.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission :
		from	to	from	to		
Chevrolet	Silverado 1500	2020	2021	-	-	Equipped with 3.0L (RPO LM2)	-
	Silverado 1500 LTD (RPO J21, VIN Digit 5 = W / Y)	2022	2022				
	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)						
	Silverado 1500	2023	2023			Equipped with 3.0L (RPO LZ0)	
	Silverado 2500HD/3500HD	2020	2023			Equipped with 6.6L (RPO L5P)	
GMC	Sierra 1500	2020	2021			Equipped with 3.0L (RPO LM2)	
	Sierra 1500 Limited (RPO J21, VIN Digit 5 = 8 / 9)	2022	2022				
	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)						
	Sierra 1500	2023	2023			Equipped with 3.0L (RPO LZ0)	
	Sierra 2500HD/3500HD	2020	2023			Equipped with 6.6L (RPOs L5P)	

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	4
Modified	Released October 25, 2021 Revised June 02, 2022 – Revised to update information under the Correction. Revised September 02, 2022 – Revised to add 2023 Model Year and RPO LM0. Revised September 29, 2022 - Ended the need for further information from the field.