

**Subject: Engineering Information - Rear Washer Hose Disconnected**

*This PI has been revised to end the need for information from the field. Please discard PIE0705.*

| Brand:    | Model:          | Model Year: |      | VIN: |    | Engine: | Transmission: |
|-----------|-----------------|-------------|------|------|----|---------|---------------|
|           |                 | from        | to   | from | to |         |               |
| Cadillac  | Escalade Models | 2021        | 2023 | —    | —  | —       | —             |
| Chevrolet | Suburban        |             |      |      |    |         |               |
|           | Tahoe           |             |      |      |    |         |               |
| GMC       | Yukon Models    |             |      |      |    |         |               |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

|                 |                                                                                                               |
|-----------------|---------------------------------------------------------------------------------------------------------------|
| <b>Version</b>  | 2                                                                                                             |
| <b>Modified</b> | Released June 13, 2022<br>Revised September 29, 2022 - Ended the need for further information from the field. |