



TECHNICAL SERVICE BULLETIN

Classification: AT20-004B	Reference: NTB20-038B	Date: October 4, 2022
------------------------------	--------------------------	--------------------------

DTC P288B STORED IN THE TCM

This bulletin has been amended. See AMENDMENT HISTORY on the last page.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2020 Titan/Titan XD (A61)
APPLIED DATES: Built before January 28, 2020

SERVICE INFORMATION

If DTC P288B (PARK LOCK SOLENOID) is stored in the TCM:

- Check Service COMM or Dealer Business Systems (DBS) National Service History to confirm if campaign R22B1 or R22A9 has been applied.

NOTE: The customer may have stated:

- The warnings shown in Figure 1 turned ON in the vehicle information display and speedometer.

AND

- Two attempts were required to shift out of Park.




Figure 1

1. Has campaign R22B1 or R22A9 already been completed?

NO: Complete the related campaign bulletin.

YES: Proceed to step 2.

2. If the conditions described above reoccur, refer to the ESM for further diagnostic information not covered by this bulletin.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
May 19, 2020	NTB20-038	Original bulletin published
July 28, 2020	NTB20-038a	TCM part number listed in CLAIMS INFORMATION footnote "(1)" has been revised
October 4, 2022	NTB20-038B	Changes made throughout

