



STAR ONLINE PUBLICATION



Case Number: S2208000016

Release Date: January 2022

Symptom/Vehicle Issue: Headlamps Or Fog Lamps Do Not Follow Steering Input When Turning

Customer Complaint/Technician Observation: Owner complains the vehicles cornering lamps/ head lamps do not illuminate when turning. Technician has observed the vehicle may have some common sales codes LMS - Auto High Beam Head Lamp Control, and LNJ or LNV front fog lamps.

Discussions: Vehicles equipped with auto high beams sales code LMS have software to control the high beam operation when the system is turned on. The high beams will turn on and off while driving based on ambient lighting levels to turn the high beams on and off.

If the vehicle is equipped with fog lamps, sales code LNJ or LNV, the fog lamp on the side of the activated turn signal will also illuminate to provide additional lighting when turning. This added illumination requires steering input along with an activated turn signal on the direction of the turn.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found