



STAR ONLINE PUBLICATION




Case Number: S2208000069

Release Date: March 2022

Symptom/Vehicle Issue: PCM Ground G929A Is Not Fully Tightened. Vehicle Does Not Start

Discussion: The customer may complain that the vehicle does not start. This may be caused by the PCM ground G929A not being fully tightened. Causing an intermittent connection.

Diagnosis: Inspect the G929A ground in the engine bay on the drivers frame rail.



Repair Procedure: Tighten ground to 10.5 Nm.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found