

Subject

**RoB DTC X0528 and/or Hybrid System Overheating Message on MIDMID**

Market

USA

Service Category

Engine/Hybrid System

Section

Cooling

Applicability

2023 Camry HV


**APPLICABLE VEHICLES**

2023

Camry HV

**CONDITION**

The customer may complain of "The Hybrid System may be overheating" displayed in vehicle alerts and further inspection may find Vehicle Control History (RoB) DTC X0528 (Generator Inverter Temperature High) stored. This issue is under investigation at this time.




**RECOMMENDATIONS**

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

**Prior to contacting TAS, attach the following to the case:**

1. Techstream file with complete Health Check, All Freeze Frame Data and Vehicle Control History (RoB) data from Hybrid Control
2. Photo of HV Water Pump Parts Identification Tag
3. Photo of Inverter Parts Identification Tag

**HV Water Pump Parts ID Tag Example**



**Inverter Parts ID Tag Example**



**LINK REFERENCES**

This Tech Tip does not contain any link references