



Technical Service Bulletin

47 Vibration/noise from brake pedal area - pedal feels different - DTC P05FF00

47 22 19 2068205/1 October 10, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT	2022 - 2023	Not Applicable	Not Applicable

Condition

Customer states:

During braking at low speeds, a vibration/pulsation is felt at the brake pedal, and/or the brake pedal feels “different”.

Workshop findings:

The following DTC and symptom code combination may be stored in the ABS/ESC Control Module -J104- (address word 0003):

- **DTC P05FF00** – *Brake pressure sensor / Sensor for brake pedal travel deviation.*

The complaint can be reproduced.

Technical Background

Not applicable.

Production Solution

Under analysis.



Technical Service Bulletin

Service

1. Read out the measured value "Adaption value offset wheel brake stiffness" and upload the log to GFF Paperless.
2. Clear DTCs in the J104 ABS/ESC control unit.
3. Bleed the brake system fully according to *ELSA>>Workshop Manual>>Chassis>>Brake System>>47 Hydraulic Components>>Hydraulic System>>Bleeding*.
4. Re-evaluate the vehicle for improvements concerning noises and brake pedal feel. If the issue has been solved, release the vehicle. If the complaint is still present, repeat the bleed procedure.



Note:

For noise complaints, please upload a video/audio file to DOC-IT with the respective VIN number.

Warranty

Claim Type	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4708		
Damage Code:	0011		
Labor Operations:	Brake system bled	4701 0750	See SRT
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 70 TU)



Technical Service Bulletin

	Road test prior to the service procedure	0121 0002	10 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB 2068205/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2068205**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.