



Service Bulletin

Bulletin No.: 20-NA-172

Date: October, 2022

INFORMATION

Subject: Remote Keyless Entry (RKE) System Operational Change for Front Trunk Function

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2020	2023	—	—	All	All

Involved Region or Country	North America, Middle East, Australia/New Zealand
Condition	Some customers may comment that the remote keyless function for the front hood button does not work.
Cause	The cause of the condition may be due to a design change to the Remote Keyless Entry (RKE) System button function for the hood. This change was implemented to reduce the chance of inadvertent activation of the hood.

Customer Information

Inform the customer that in order to activate the hood with the Remote Keyless Entry (RKE) System, they must now press the hood button once and then press and hold the hood button down the second time to activate the hood release.

Failure to hold the button down on the second button press will not open the hood.

Please communicate the function change with the customer.

Parts Information

No parts are required for this repair.

Version	2
Modified	Released August 27, 2020 Revised October 04, 2022 – Added the 2021–2023 Model Years and Australia/New Zealand to Involved Region or Country section.

Additional SI Keywords: FOB, FOBS, transmitter

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION