



SIB 63 03 22

2022-09-07

WELCOME LIGHT STARTS UP ERRATICALLY

**MODEL**

E-Series	Model Description	Production Date
G20	3 Series Sedan	January 07, 2022 to est. January 05, 2023

**SITUATION**

When unlocking the vehicle, the welcome light in the headlight “lights up erratically.”

**CAUSE**

Software error in the FLM (Front Light Electronics) control module.

**Note: This complaint will not cause a CCM (Check Control Message)/fault code to appear.**

**CORRECTION**

Program the vehicle to I-level S18A-23-03-500.

**This software is expected to be released 03/2023** (pending verification).

**PROCEDURE**

This bulletin will be updated once this ISTA version is close to being released.

**PARTS INFORMATION**

Do not replace any parts.

**CLAIM INFORMATION**

This Service Information bulletin provides technical, diagnostic, and future repair-related information.

The BMW software solution, when available on or after March 2023, will be covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks, or the BMW Certified Pre-Owned Program that applies, unless the vehicle has an open programming and encoding campaign repair.

The Claim Information section for this Service Information will be updated then accordingly.

**FEEDBACK REGARDING THIS BULLETIN**

Technical Feedback	To submit feedback for the technical topics of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department