

2022 Ascent

LOW FLOW FROM KITCHEN SINK. KINK IN LINE/IMPROPER INSTALL POSITION LINE AND ANTI KINKK DEVICE IN PROPER PLACE HR-
0.7 0.50 approved.

2022 Ontour

Line 1: KITCHEN SINK

Complaint: CUSTOMER STATES THAT THE PULL hose AT THE KITCHEN SINK DOESN'T SIT PROPERLY

Cause: FAUCET OFF CENTER

Correction: REMOVE FAUCET SET IN PLACE TIGHTEN HOSE NOW CENTERED

Labor request: 0.50 0.50 approved.